GENERAL AND REVENUE SECRETARIAT.

1898–99

~~191~~.

(Inward)

File No. 140

Serial Nos.

Papers Filed.

*Month*_____

SUBJECT.

Repairs to the Chitra Gopuram attached to the Srikanteswaraswami Temple at Nanjangud

PREVIOUS REFERENCES. LATER REFERENCES.

ಇಂತಿ ನಿಮ್ಮ ವಿಶ್ವಾಸಿ

ಡೆಪ್ಯುಟಿ ಕಮಿಷನರ್

ಚಿತ್ರದುರ್ಗ ಜಿಲ್ಲೆ

ಬ ಕಾರ್ಯಾಲಯ ನೇಮಕದ ಮೇರೆಗೆ 1898ನೆ
ಇಸವಿ
ಸಲಾಂಪೂರ್ವಕ ಸಲ್ಲಿಸುವಿಕೆ

ಡೆಪ್ಯುಟಿ ಕಮಿಷನರ್.

ಕಾಗಿನೆಲೆ ಕನಕಗುರುಪೀಠದ ಪೀಠಾಧಿಪತಿಗಳಾದ ಶ್ರೀ ನಿರಂಜನಾನಂದಪುರಿ ಸ್ವಾಮೀಜಿಯವರ ಸೇವಾರ್ಥ ಕಾಗಿನೆಲೆಯಲ್ಲಿ ಕನಕಗುರುಪೀಠದ ಸಮೀಪ ಸಾರ್ವಜನಿಕರ ಉಪಯೋಗಕ್ಕಾಗಿ ಸಾರ್ವಜನಿಕ ಶೌಚಾಲಯ ಕಟ್ಟಡ ನಿರ್ಮಾಣ ಕಾಮಗಾರಿಯನ್ನು ಕೈಗೊಳ್ಳಲಾಗಿದ್ದು, ಸದರಿ ಕಾಮಗಾರಿಯನ್ನು ಪೂರ್ಣಗೊಳಿಸಲು ಸಾರ್ವಜನಿಕರಿಂದ ಧನಸಹಾಯ ಕೋರಿ ಸ್ವಾಮೀಜಿಯವರು ಮನವಿ ಮಾಡಿಕೊಂಡಿರುತ್ತಾರೆ. ಸದರಿ ಮನವಿಯನ್ವಯ ಕಾಗಿನೆಲೆ ಕನಕಗುರುಪೀಠದ ಸಮೀಪ ಸಾರ್ವಜನಿಕರ ಉಪಯೋಗಕ್ಕಾಗಿ ಸಾರ್ವಜನಿಕ ಶೌಚಾಲಯ ಕಟ್ಟಡ ನಿರ್ಮಾಣ ಕಾಮಗಾರಿಯನ್ನು ಕೈಗೊಳ್ಳ

ಅಲ್ಲಿ ಕೆಲಸಗಳು ಇಂದಿನಿಂದ ಪ್ರಾರಂಭವಾಗಿ ಮುಂದಿನ ಸೆಪ್ಟೆಂಬರ್
ಅಂತ್ಯದೊಳಗೆ ಪೂರ್ಣಗೊಳ್ಳಬೇಕು. ಈ ಕೆಲಸಗಳಿಗೆ ಸಂಬಂಧಿಸಿದಂತೆ
ಯಾವುದೇ ಅಡೆತಡೆಗಳು ಬಂದಲ್ಲಿ ಅವುಗಳನ್ನು ಸಕಾಲದಲ್ಲಿ
ಬಗೆಹರಿಸಿಕೊಳ್ಳಬೇಕು.

Estimate of the probable Cost of repairing a Teakwood building situated on the North-East of Sree Conjeeveraswarmi Temple Tolugu Ramayya

Description of Works	Number	Dimensions Length	Breadth	Depth	Contents		Total Contents
Down Stairs							
Central Hall							
Teak wood							
Removing old and worn out joists and replacing the same with new ones in							
3.5.6.7.8 & 9 Punkah ams.	17	7	4"	5"	16½		
Beam do — do — in Room No 1	1	9½	6"	8"	3		
do — do — in room No 2	1	10½	4"	5"	1½		
Another do do - room in do	2	5½	4"	5"	1½		
do — do small joists	3	3¾	4"	5"	1½		
do — do — do - in Room No 4	2	9½	4"	5"	2¾		
do — do — do — do — —	1	9½	4"	5"	1⅜		
do — do — do - Entrance room	1	9½	4"	5"	1⅜		
Total					cft	cft	
Teak wood door Frame being heavy	1	6	3		18	cft	
Some wood windows with Iron bars	11	2	"	2½	55	cft	55
Chunam plastering							
Walls Roofs and Floors							

(Chunnam Plastering Contains 51

door ways in the Centre Hall	"	"	"	"	"	sqs	1¼
Room No 1	"	"	"	"	"	do	1¼
do — No 2	"	"	"	"	"	do	1¼
— do — do —	1	8½		7	60		
door jambs and the floor	"	"	"	"	"	sqs	1½
Walls of room No 3	"	"	"	"	"	sqs	1
Terrace (inside of the roof)	1	96	8¾	"	540		
Total Plastering						sqs	113¾
Brick in chunnam							
Chimming	2	2¾	1½	1½	12⅓	cft	12⅓
Chunnam Concrete & Smoothing							
— Floor of Room No 1	"	"	"	"	3		
— do — do — No 3	"	"	"	"	10	cft	13
Stone in mortar							
Scraping of Cracks and							
putting Stone Slabs in 3 places							
to hold fast	3	1½	½	½	1½	cft	1½
Brick masonry							
Wall	1	167	"	7½	802½		
Ceiling	6	7½	6½	"	292		
— do	8	6	"	6	288		
Parapet wall of the Central hall	1	6½	"	2¾	43		
Room No 1	1	39	"	8	312		
Ceiling	1	10	8½	"	93		
Another room in room No 1	1	37		8	296		
Ceiling	1	10	8½		85		
Room No 2	1	55		8	440		

(Chamman Washing Continued)

Ceiling —	/	18	8½ ..	163
Another room No 2	/	33	.. 7	231
Ceiling	/	18½	8 ..	68
Room No 3	/	113½	.. 8	08
Ceiling	/	96	8¾ ..	0
Room No 4	/	3¼	.. 8	66
Ceiling	/	8½	8½ ..	2¼
Room No 1 in room No 4	/	54	.. 8	32
Ceiling	/	8½	8½ ..	157
Room No 2 in room No 4	/	3¼	.. 8	66
Entrance	/	5	.. 8	60
Wall including the arch	/	8	.. 8	6
Total				180
deduct				
Doors 2 2 x 6 x 3				396
Windows 11 x 2 x 2				55
Total				57
Total white washing Sec				57¼
Yellow color washing				
Cornice and of walls of				
Central hall	/	87	. ½	53½ 4n ½
Repairing a door				

Estimate of the 2nd floor stories

Detail of works	No of Numbers	Dimension Length	Dimension Breadth	Dimension Depth	Contents		Total Contents
Teak wood doors							
door to the hall	1	6	3	..	18		
do — do —	1	5½	2 10/12	..	15½		
— do — Room No 1	1	5 3/4	3	..	17¼		
— do — do No 3	1	5½	3	..	16½		
Total						49	67¼
Surki Mortar							
Floor of the room near the Stairs	..	..	..	..	1½	49	1½
~~Sitaphoi on the Chaeth~~							
in ~~parapet walls~~ Room No 1 of	..	..	..	..	..	49	1¼
do — do No 3	....	..	..	..	..	do	1¼
Total	-	..	-	-	..	49	4
Surki Mortar							
Floor of the hall opposite to cook room taking off old Mortar each side and removing old Mortar 1½ inches each side and filling in the same over the roof	..	..	..	..	30		
Total					..	Rgk	41
do — do - inserting the cloth wetted with tar do — do —					47½		
do — do — the same in the last Storey					5		
Total							

Do 2nd Do - Do another Cargo						
Crack to be built brick on edge on each side and shored let constructed the whole in Brick Lurki mortar & Sloped Stone in Mortar	..	..	..	..	..	Kgs 11
Scraping out the cracks in the walls of room No 3 in the hall and putting Stone Slabs in 3 places to hold fast	6	1½	½	½	4	
do do do do	1	1½	½	½	1	
Scraping out the Cracks in Parapet walls and putting Stone Slabs in 6 places of the last Storey	6	1	½	½	1½	
Total	..	..	..	..	..	off 6½
Chunnam plastering						
Stairs to the upper storey	..	..	..	..	¾	
Sundry					1¼	
E to the hall of the upper storey	..	..	..	..	1	
do of room No 2	..	..	..	..	1¼	
do do No 3	..	..	..	..	1¼	
window of room No 3	..	..	..	..	¼	
Walls of the building (out side) from ground to the height of 2½ ft to one side and to the top of walls and other prepairs	..	..	..	..	5½	
Total					Rs/ 11-	

White washing

Steps

Wall leading to the Steps	1	44		3	33
Room coming from up Stairs	1	35		7½	262
Room above wall	1	8		3	24
Upper Storry (Hall)	1	74¾		7	521
Room No 1	1	34		8	272
—do— No 2	1	35⅓		7½	262
—do— No 3	1	35⅓		7½	262
Hall opposite to cook room	1	56		7½	345
Room Upper storry	1	46¾		8½	346
Room No 2	1	33		8	264
—do— do No 3	1	23		8	184
Total					3085
deduct					
Doors 2×6×3					216
Windows 7×2½×2					35
—do— 2×1½×1					3
—do— 3×3½×2¾					27
—do— 1×1¾×1¾					3
Wall 1×8×3					24
Window 1×1½×1½					2¼
arches 8×6¾×4½					96
Total					407
Total White washing					Rps 263¼

Yellow washing

Ends of the walls round the Room	1	35	..	1/2	18		
Hall of the upper storey	1	8 1/3/4	..	1/2	41		
Room No 1	1	37	..	1/2	19		
Do — No 2	1	9/3	..	1/2	20		
Total yellow					94	Yds	1
Spouts for letting out rain water							
each 2½ ft long	-	-	-	-	..	No	5
do — do — 3 ft long do						No	7
Iron bars for windows in							
the upper storey each 3 ft long							3
Repairing Cornice in down Storey					58		
do — do — Upper Storey					58		
White washing							
Front, down & upper stories	..	..	..	..	..	Yds	10 1/3
Sides down & upper Stories	..	..	..	..	..	Yds	8
Front & Sides of the parapet							
of the last storey	1	100	3½	..	1.50		
Total						Yds	20.
Constructing a well			Seen				
Petty repairs —							

Abstract

Items	Ror	Rate			Quantity	Amount
Teak wood of Joists	cft	2	8	a	29½ ft	73-12-0
do ——— do — doors	sqft	a	8	a	85¼	41-4-0
Hone wood Windows with Iron bars.	~~55~~ cft	1	4	a	55	68-12-0
Brick in chunnam	cft	a	3	a	64	2-0-0
Chunnam plastering	sqrs	2	8	a	23	57-8-0
Chunnam Concrete	cft	a	3	a	13	2-7-0
Stone in mortar	cft	a	4	a	8	2-0-0
White washing	sqrs	-	~~4~~	a	94	23-8-0
Surkhi mortar	sqrs	-	3	6	4	0-14-0
Filling in cracks in Surkhi mortar	Rqft	a	2	a	41	5-2-0
do —do in Tar cloth	Rqft	a	6	a	97½	36-0-0
cracks Brick on edge & Hoped	Rqft	-	8	a	4	5-8-0
Yellow washing	sqrs	-	6	a	1½	0-9-0
repairing door frame & door	Lump Sum					0-8-0
Spouts 2½ ft long & 3 ft long Nos 5 & 7 each 8	Nos & qs	..	..		Nos 57	6-7-0
Iron bars for windows each 3 ft long	each	a	4	a	Nos 38	8-4-0.
Repairing the Cornice 58 ft length	Lump Sum					2-8-0
do —do— Plastering	Rqft	a	2	a	58	7-5-0
Constructing a well	Lump Sum					125-00.
Total						469-4-0
for other repairs	Lump Sum					15-00.
Total						484-4-0
Contingence @ 5 Per cent						15-12-0
Grand total Rupees						500-0-0

Martha Dorothy Iyengar
Work Inspector
8/21-7-28.

Muz. 7]

127.

ರೂಬಕಾರಿ

ಮೈಸೂರು ಗೌರ್ನಮೆಂಟ್ ಮುಜರಾಯಿ ಇಲಾಖಾ

ಬೆಂಗಳೂರು ನೇ ದೂಹೆ

189 ನೇ ಇಸವಿ ಮೊಕ್ತಾಂ

By Order,

Muzrai Secretary.

ಸಿಬ್ಬಂದಿಗಳ ಮಾಹಿತಿ ಸಂಗ್ರಹಿಸುವ ಬಗ್ಗೆ

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ ಈ ಕಛೇರಿಯಲ್ಲಿ ಕೆಲಸ ನಿರ್ವಹಿಸುತ್ತಿರುವ ಸಿಬ್ಬಂದಿಗಳ ಮಾಹಿತಿಯನ್ನು ಈ ಕೆಳಕಂಡ ಪ್ರಕಾರ ಸಂಗ್ರಹಿಸಿ ಕೊಡಲು ಸೂಚಿಸಿದೆ.

ಸಿಬ್ಬಂದಿಗಳ ಹೆಸರು, ಹುದ್ದೆ, ಸೇವೆಗೆ ಸೇರಿದ ದಿನಾಂಕ, ಹುದ್ದೆಗೆ ಸೇರಿದ ದಿನಾಂಕ, ಜನ್ಮ ದಿನಾಂಕ, ಶೈಕ್ಷಣಿಕ ಅರ್ಹತೆ, ಜಾತಿ, ಪ್ರವರ್ಗ, ಸಂಬಳದ ಶ್ರೇಣಿ, ಪ್ರಸ್ತುತ ಮೂಲ ವೇತನ, ಸಂಬಳ ಪಡೆಯುತ್ತಿರುವ ಬ್ಯಾಂಕ್ ಹೆಸರು, ಖಾತೆ ಸಂಖ್ಯೆ, ಪಿ.ಎಫ್. ಖಾತೆ ಸಂಖ್ಯೆ, ಪಿ.ಎಫ್. ಖಾತೆಯಲ್ಲಿ ಜಮೆಯಾಗಿರುವ ಮೊತ್ತ